

## Courtesy Safety Notice: AustriAlpin COBRA® buckles


Fulpmes, 14 January 2016

Dear valued clients,

it has come to our attention that in an extremely small quantity (0.0000005% = 1 out of 2 million) of COBRA® buckles there may exist parts where the rivets have **not been press fixed**.


This results in the rivets being loose and the release clips detach. COBRA® buckles in all different versions and sizes can be affected. As we are dedicated to the 100% function, performance, quality and safety of our products, we ask all our clients and end users of COBRA® buckles to **do a visual check**:

### Correct



The rivet shows an embossing in the form of a ring on both the front and back sides of the rivet.  
Do not manipulate the rivets by mechanical action.

### NOT Correct



The rivet does not show any circular embossing.

If you notice a buckle that is NOT riveted or you do have any concerns, STOP USING the product immediately and get in contact with us: [office@austrialpin.at](mailto:office@austrialpin.at) or via phone **+43 522 56 52 48**

We would like to apologize for the inconvenience and are kindly asking for your understanding.