

Gin Gliders Safety Notice: G-Lite Rescue Parachute



G-Lite deployment bag (G-Lite 32 and 39)

Routine inspection and testing have revealed that material degradation and/or damage may result in the breaking of the rubber bands that close the inner bag of the G-Lite rescue parachute, and thus a failed deployment.

Pilots flying with the G-lite should replace the rubber bands on their deployment bags with textile cord (shock cord) before their next flight.

Please refer to the instructions in the [manual](#) on the Gin website, and Gin's YouTube [instruction video](#). The [original Gin safety notice](#) is also available on their website.

Gin will provide free replacement rubber band packs for all G-Lite deployment bags; contact the dealer from whom you bought your reserve. Instructions in the link apply only to the G-Lite – other Gin rescues and inner bags are not affected.